

REMARKS / ARGUMENTS

In the specification, the Description of the Embodiments has been corrected to properly coincide with the Drawings and Claims based on the Examiner's comments and feedback during the Office Interview of August 02, 2006 . No New Matter has been added.

Furthermore the Drawings have been corrected as well to correct some misplaced numerical callouts, again based on the Office Interview previously stated. No New Matter has been added.

Claims 1 and 8 have been amended to more clearly define the scope to the application with respect to the specification and the intent of the application. No New Matter has been added.

All other claims remain in this application and concur with the Examiner's comments during the stated Office Interview.

The application presented submits the position that through the drawings, specification, and claims, the orienter detail is depicted to provide rotation to the rotatable housing of the orienter only, located between the motor and drill bit. This is more clearly defined in the amended Claim 1 as presented earlier.

Appl. No. 10/731,496
Amdt. dated August 22, 2006
Reply to Office action of May 23, 2006


The amended specification, claims, and drawings do not present any New Matter with regard to additional material to be found in this application.

Because the amended claim does not describe what is in the prior art the amended claim is now in condition for allowance.

Respectfully Submitted,

David M. Camp

Inventor

A handwritten signature in black ink, consisting of a series of loops and a horizontal line, positioned over a horizontal line.

August 22, 2006

AMENDMENT TO THE DRAWINGS

The following corrections were made to the following annotated drawings:

- Fig 2
 - Line was missing in drawing adjacent to Item 36. Line has been inserted so as to
 - clearly identify the division between Items 32 and 34
- Fig 3.
 - Line as missing in drawing adjacent to Item 36. Line has been inserted so as to
 - clearly identify the division between Items 32 and 34
- Fig 4.
 - Numerical call out for Item 24 was moved to provide clarity
 - Item 32 was identifying the wrong item and has been corrected to illustrate the appropriate component

Annotated Drawing Sheet




Fig. 2




Fig. 3

Annotated Drawing Sheet




Fig. 4




Fig. 5